

ANNUAL SURVEYS.

13412

No. 240 Survey held at Whitstable Date 21 May 1847
on the Gun "Lige" Master Blackland
Tonnage 88 Built at Milton When built 1838
By whom built 59 Owners D. J. Alston
Port belonging to London Destined Voyage - India
If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 5312 Port of London Classed 12 A1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Painters, and Crutches <u>dry</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>sound</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>good</u>	Sails <u>do</u>
Planksheers <u>good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>2 D S 1 K</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Coppered <u>1145</u> <u>upon felt</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion, The appears in good and efficient condition and may remain as capped Hartman

Committee Minute 28 May 1847

Character assigned 12 A1

Shed up # 2. 2. W

Certificate (if required)

No. 236 Survey held at London Date 15 May 1847
on the 1st Golden Spring Master N. Poole
Tonnage 116 Built at Lyons When built 1821
By whom built - Owners Shpherd
Port belonging to London Destined Voyage India
If Surveyed Afloat or in Dry Dock London Ship

Last Survey, No. 1127 Port of London Classed 12 A1

The present Condition of the

Decks <u>good</u>	Treenails <u>good & new</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>good</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Painters, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>sound</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>good</u>	Sails <u>do</u>
Planksheers <u>good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>3 D S 1 K</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>45</u> <u>do</u>	Standing & Running Rigging <u>do</u>

General Observations and Opinion, The new Mast now put in the lower deck

Beam Clampet is in an efficient condition fit for the
conveyance of any and perishable Cargos to & from the ports
of the world and may remain

Committee Minute 28 May 1847

Character assigned 12 A1

Certificate (if required)