

# REPORT of SURVEY for REPAIRS.

Change of Owners  
13453

No. 1085 Survey held at Whitstable Date May 21<sup>st</sup> 1847  
on the Gutta "Videx" Master Mr. Baxford  
Tonnage 98<sup>45</sup> Built at Scroes When built 1824  
By whom built - Owners D. J. Alston  
Port belonging to London Destined Voyage Danish  
If Surveyed Afloat or in Dry Dock Afloat and upon the ways

Last Survey, No. 297 Classed Res. Reg. 44.1

Port Portsmouth

REPAIRS At the present time new Channels and Channel works  
Caulked all over from the keel up including the decks  
Shutted with yellow paint upon feet,

## Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Copstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stenson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>for when in</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>2 B 1 1/2 M do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Yellow Paint upon feet</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, It appears in good and efficient condition  
and may remain as repaired.

The Amount of Fee.....£ : 10 : - is received by me,

Certificate (if required) : 5 : 4

Committee's Minute 18th June 1847

Character assigned Res. Reg. 44.1

Lloyd's Register  
Foundation