

# REPORT of SURVEY for REPAIRS.

*Group of Owners*

13475  
No. 22  
1847

No. 527 Survey held at London Date 5 June 1847  
on the Bark "Collingwood" Master Crawford  
Tonnage 637 Built at Switzerland When built 1847  
By whom built                      Owners J Dunbar  
Port belonging to London Destined Voyage Catcutta  
If Surveyed Afloat or in Dry Dock in East India St.

Last Survey, No. 3202 Classed 10 A 1

Port Switzerland  
REPAIRS at Present looked hung in Shores Caulked all up  
over the decks a 3/4" Galn Keel fitted bottom fitted  
and Coppered with Yellow Metal

## Present Condition of the

Decks <u>Caulked Good</u>	Timberails <u>Caulked in bottom</u>	Windlass and Capstan
Waterways <u>                    </u>	Breasthooks and Stemson <u>Good</u>	Pumps
Comings <u>                    </u>	Transoms, Pointers, and Crutches <u>                    </u>	Boats <u>Well</u>
Upper Deck Beams & Fastenings <u>                    </u>	Timbers of the Frame <u>                    </u>	Masts, Yards, &c. <u>Found</u>
Lower Deck Beams & Fastenings <u>                    </u>	Keelsons <u>                    </u>	Sails <u>                    </u>
Planksheers <u>                    </u>	Clamps and Shells <u>                    </u>	Anchor No. of <u>                    </u>
Sheerstrakes <u>                    </u>	Ceiling <u>                    </u>	Cables <u>                    </u>
Topboards <u>                    </u>	Rudder <u>                    </u>	Hawsers and Warps <u>                    </u>
Wales <u>                    </u>	<u>Copper 1/4" Metal on felt</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>                    </u>	<u>New Sheet Ply</u>	

General Observations and Opinion,  
This Vessel is in excellent Condition and  
may remain as is

The Amount of Fee.....£ 3 : is received by me J. H. Ritchie  
Certificate (if required) :  
Committee's Minute 27 June 1847  
Character assigned 10