

# ANNUAL SURVEYS.

13481

Recd 11/19/84

No. 12005 Survey held at Sunderland Date June 24 1847  
 on the Rk Ralph Bernal Master McLaren  
 Tonnage 314 Built at Sunderland When built 1835  
 By whom built \_\_\_\_\_ Owners McLaren & Co  
 Port belonging to Sunderland Destined Voyage New Zealand  
 If Surveyed Afloat or in Dry Dock Afloat

Continued Was Classed 3 A 1

Last Survey, No. 12005 Port of Sunderland

The present Condition of the		
Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways "	Breasthooks and Stenson "	Pumps "
Comings "	Trensons, Pointers, and Crutches <u>good</u>	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame <u>strong &amp; sound</u>	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers "	Clamps and Shelves "	Anchors No. of <u>3 Bows 18 in 2 Hedges</u>
Sheerstrakes "	Ceiling "	Cables <u>well found</u>
Topsides "	Rudder "	Hawsers and Warps "
Wales "	Copper <u>4 1/2</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter "		

General Observations and Opinion. New wind sails, appears in all respects in good condition sufficient to retain her present class

Committee Minute 22 July 1847  
 Character assigned Class 3 A 1

Certificate (if required)

No. 12003 Survey held at Sunderland Date June 14 to 25 1847  
 on the Rk Thomas Joseph Crisp Master W. H. H. H.  
 Tonnage 314 Built at Sunderland When built 1840  
 By whom built \_\_\_\_\_ Owners Crisp  
 Port belonging to Sunderland Destined Voyage Capetown & Cape of Good Hope  
 If Surveyed Afloat or in Dry Dock Afloat on the ways

Classed PA 1

Last Survey, No. 12003 Port of Sunderland

The present Condition of the		
Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways "	Breasthooks and Stenson "	Pumps "
Comings "	Trensons, Pointers, and Crutches "	Boats "
Upper Deck Beams & Fastenings "	Timbers of the Frame <u>strong &amp; sound</u>	Masts, Yards, &c. "
Lower Deck Beams & Fastenings "	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers "	Clamps and Shelves "	Anchors No. of <u>3 Bows 18 in 2 Hedges</u>
Sheerstrakes "	Ceiling "	Cables <u>well found</u>
Topsides "	Rudder "	Hawsers and Warps "
Wales "	Copper <u>4 1/2</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter "		

General Observations and Opinion. Examined from the upper to the gunwale & the stowage's examined & all in good condition to retain her present character

Committee Minute 2 July 1847  
 Character assigned Class 3 A 1

Certificate (if required)