

ANNUAL SURVEYS.

13573

No. 16 Survey held at London Date July 28th 1847
 on the Ship "Lucan" Master Nash
 Tonnage 1254 Built at London When built 1842
 By whom built 1847 Owners Nigam
 Port belonging to London Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock In Mess^r Nigam's Dry Dock

Last Survey, No. 19 Port of London

Classed 12 A 1

1846

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stenson } <u>good when seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>discovered</u>	Keelsons	Sails } <u>all sufficient</u>
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	<u>Wales not on full planks</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The Wales now Caulked and Fore Mast new. She is in good condition eligible to remain as Classed A 1

Committee Minute

16th July 1847

Character assigned

12 A 1 J. Martin M. M. M.

Certificate (if required)

No. 115 Survey held at London Date July 28th 1847
 on the Ship "Crested" Master S. Sennick
 Tonnage 529 Built at Bristol When built 1835
 By whom built Hillhouse Owners Hillhouse
 Port belonging to Bristol Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock In Mess^r Metchers Dry Dock

Last Survey, No. 19579 Port of London

Classed 12 A 1

46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stenson } <u>good when seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. } <u>In good order</u>
Lower Deck Beams & Fastenings } <u>discovered</u>	Keelsons	Sails } <u>all sufficient</u>
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales } <u>discovered</u>	<u>Wales not on full planks</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

The Owners now request that this ship might be surveyed with a view to her Continuation but they desire to examine the bottom and the wood sheathing off the lower part of the hull and the lower deck.

Committee Minute

16th July 1847

Character assigned

12 A 1

J. Martin M. M. M.

Certificate (if required)