

# ANNUAL SURVEYS.

1354

No. 137 Survey held at LONDON Date 19 July 1847  
 on the "Dark Gullat Muaro" Master W. J. Digby  
 Tonnage 258 Built at Shields When built 1828  
 By whom built \_\_\_\_\_ Owners Digby  
 Port belonging to LONDON Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock in Bullhead Dock

Last Survey, No. 12416 Port of LONDON Classed 10  
1842 Reg. 7 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>apparently Good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, Sc. <u>well</u>
Lower Deck Beams & Fastenings _____	Keelsoas _____	Sails <u>found</u>
Planksheers <u>Caulked</u>	Clamps and Shelves _____	Anchors No. of <u>2, 1, 1</u> <u>and</u>
Sheerstrakes _____	Ceiling _____	Cables <u>sufficient</u>
Topsides _____	Rudder <u>new false stem post and</u>	Hawsers and Warps <u>4</u>
Wales _____	<u>Keelsoas bands refilled</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>Copper 4 Metal Key on</u>	

General Observations and Opinion,  
at present bottom stripped hung in shores caulked  
from the keel up and bottom treenailed with  
yellow metal on false stem post and  
new false stem post and  
bands replaced - in efficient condition  
 Committee Minute 27th July 1847  
 Character assigned Well and any Certificate (if required) \_\_\_\_\_

No. 84 Survey held at LONDON Date 24 22 July 1847  
 on the "Bell" Master Sa' Mitchell  
 Tonnage 345 Built at Sunderland When built 1845  
 By whom built \_\_\_\_\_ Owners Smith & Bell  
 Port belonging to LONDON Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock in Fox Kaff Dock

Last Survey, No. 608 Port of LIVERPOOL Classed 11 A 1

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame <u>Good</u>	Masts, Yards, Sc. <u>well</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsoas _____	Sails <u>found</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables <u>sufficient</u>
Topsides _____	Rudders _____	Hawsers and Warps _____
Wales _____	<u>Copper 4 Metal Key on</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<u>the bottom July 1847</u>	

General Observations and Opinion,  
at present bottom stripped, caulked and treenailed  
with yellow metal on the bottom - in efficient condition  
 Committee Minute 27th July 1847  
 Character assigned Well and any Certificate (if required) \_\_\_\_\_