

ANNUAL SURVEYS.

13583

No. 578 on the Ship Stag Survey held at London Date August 6 184 7
 Tonnage 543 Built at Swindland Master Henry
 By whom built 670 Owners W Green When built 1842
 Port belonging to London Destined Voyage Port Phillip
 If Surveyed Afloat or in Dry Dock In Green's Dry Dock

Class of Ship

Last Survey, No. 12551 Port of London Classed 10 A 1
46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good when seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order and sufficient</u>
Lower Deck Beams & Fastenings <u>ditto when seen</u>	Keelsons <u>d^o</u>	Sails <u>ditto</u>
Plank sheers	Clamps and Shells <u>d^o</u>	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Oppsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Soles <u>d^o</u>	<u>Yellow Metal new run upon belt</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,

Now done. The Yellow Metal stripped off, hung in Shores caulked outside and the Bottom re-sheathed with Yellow upon Belt. She appears to be in good condition

Committee Minute 10th Aug 184 7 eligible to remain as Classed A 1

Character assigned 10 A 1 George J. Martin Certificate (if required)

No. 29 on the Ship Marion Survey held at London Date August 6 184 7
 Tonnage 544 Built at Calcutta Master McKortie
 By whom built London Owners Gladstones When built 1834
 Port belonging to London Destined Voyage Hobart Town China
 If Surveyed Afloat or in Dry Dock In Green's Dry Dock

Last Survey, No. 13192 Port of London Classed 12 A 1
46. 4. 2m 4

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good when seen</u>	Pumps <u>new</u>
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order and sufficient</u>
Lower Deck Beams & Fastenings <u>ditto when seen</u>	Keelsons <u>d^o</u>	Sails
Plank sheers	Clamps and Shells <u>d^o</u>	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Oppsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Soles <u>d^o</u>	<u>Yellow Metal 1/4" or 1/2" on belt</u>	Standing & Running Rigging <u>Laminated new</u>
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,

Deck & to examine Bottom about half a dozen Sheets expended in patching Yellow Metal, and both sides new of Iron. She is in good condition and appears to be fit to remain as Classed A 1
 Committee Minute 10th Aug 184 7
 Character assigned 12 A 1 George J. Martin Certificate (if required)