

ANNUAL SURVEYS.

No. 157 Survey held at London Date Aug 7 1847
 on the Mary Ann Master Gay
 Tonnage 207 Built at Spurwade When built 1828
 By whom built — Owners Guinep
 Port belonging to London Destined Voyage Alger Bay
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 12904 Port of London

Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>do</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Sheers <u>Good</u>	Clamps and Shells <u>do</u>	Anchors No. of <u>do</u>
Strakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Sides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Plates</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Is in good and efficient condition
and may remain as is

Master
W. H. H. H.

Committee Minute

17 August 1847

Character assigned

12 D 1 LQ

Certificate (if required)

No. 1 Survey held at London Date Aug 14 1847
 on the St. Spirit Master Hobbs
 Tonnage 46 Built at Shouham When built 1845
 By whom built Doyle Owners Doyle
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 134 Port of Shouham

Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>	Pumps <u>—</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>—</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Masts, Yards, &c. <u>—</u>
Lower Deck Beams & Fastenings <u>—</u>	Keelsons <u>—</u>	Sails <u>—</u>
Plank sheers <u>Good</u>	Clamps and Shells <u>—</u>	Anchors No. of <u>—</u>
Sheerstrakes <u>—</u>	Ceiling <u>—</u>	Cables <u>—</u>
Top sides <u>—</u>	Rudder <u>—</u>	Hawsers and Warps <u>—</u>
Wales <u>—</u>	Copper <u>—</u>	Standing & Running Rigging <u>—</u>
Plank (Bottom) and Counter <u>—</u>		

General Observations and Opinion, Is in good and efficient condition
and may remain as is

© 2019

Lloyd's Register
 Foundation

Committee Minute

17 August 1847

Character assigned

12 D 1 LQ

Certificate (if required)