

ANNUAL SURVEYS.

13660

No. 42 Survey held at London Date Aug²⁴ to 184 7
 on the "Bague Indian" Master D. English
 Tonnage 99³/₄ Built at Hull When built 1839
 By whom built Wm Gibson Owners Wm Gibson
 Port belonging to Hull Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock In Mess^{rs} Hatcher & Sons Dry Dock

Last Survey, No. 1107 Port of London Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good otherwise</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>slight</u>	Keelsons <u>d^o</u>	Sails <u>and sufficient</u>
Planksheers	Clamps and Shelves <u>d^o</u>	Anchor No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>yellow metal non-raw</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,
None done. A pair of Diagonal Staple Standard Wires introduced under Deck Beam, and across Stern Timbers to secure the Quarters. Chocks driven into Gun Courses, above and below to support Clamps and Ceiling, yellow metal stripped off Caulked
 Committee Minute 20th Aug 1847 184 Males to keel and the Bottom re sheaths with yellow metal upon hull. She is in good condition & fit to remain as classed
 Character assigned 12 A 1 Wm Gibson Certificate (if required)

No. 43 Survey held at London Date Aug²⁵ & 13 184 7
 on the "Ship Severn" Master Wm. Gann
 Tonnage 58¹/₂ Built at Scarbro' When built 1847
 By whom built Mess^{rs} Tindall Owners Mess^{rs} Tindall
 Port belonging to Scarbro' Destined Voyage Geylon
 If Surveyed Afloat or in Dry Dock In Mess^{rs} Tindall's Dry Dock

Last Survey, No. 145 Port of Scarbro' Classed 13 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good otherwise</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>slight</u>	Keelsons <u>d^o</u>	Sails <u>and sufficient</u>
Planksheers	Clamps and Shelves <u>d^o</u>	Anchor No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>yellow metal non-raw</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>		

General Observations and Opinion,
The Bottom from Wales to keel non sheathed with yellow metal upon plain Paper. She is in good condition and appears entitled to remain as classed
 Committee Minute 21st Aug 1847 184
 Character assigned 13 A 1 Wm. Gann Certificate (if required)