

REPORT of SURVEY for REPAIRS.

No. *66* Survey held at *London* Date *12 July* 184*7*
 on the *B.K. City of Adelaide* Master *Hains Esq.*
 Tonnage *288* Built at *Swiss* When built *1838*
 By whom built _____ Owners *M^r Cutcher Allen*
 Port belonging to *London* Destined Voyage *Cape of Good Hope*
 If Surveyed Afloat or in Dry Dock *in Ratcliff Croft Dock*

Last Survey, No. *743* Classed *51*
 Port *Swiss* *1845 Cal. 2 yr A1*

REPAIRS at present bottom stripped Caulked and Recoppered
 with Yellow Metal on tarred paper. New hog
 Kelson fitted & planer "Elm" - two additional
 hold beams have been put in and six pairs
 of additional iron hanging knees fitted to the
 hold beams - and hold shelf fastened
 Main Mast out & fresh and fore rigging refitted

Present Condition of the

Decks <i>Good</i>	Treenails <i>apparently Good</i>	Windlass and Capstan <i>Good</i>
Waterways <i>Caulked</i>	Breasthooks and Stewson _____	Pumps _____
Cornings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <i>Sufficient</i>
Lower Deck Beams & Fastenings <i>much new</i>	Keelsons <i>New hog</i>	Sails _____
Plank sheers <i>Caulked</i>	Clamps and Shells _____	Anchor No. of <i>3</i>
Sheerstrakes _____	Ceiling _____	Cables <i>Sufficient</i>
Topsides _____	Rudder _____	Hawsers and Warps <i>New look stings</i>
Wales _____	Copper <i>Y Metal new</i>	Standing & Running Rigging _____
Plank (Bottom) and Counter _____	<i>on paper only</i>	

General Observations and Opinion,

This vessel is in excellent condition and may continue as shipped

The Amount of Fee £ *7* is received by me, *W. H. H. H.*

Certificate (if required) _____

Committee's Minute *31 Aug 1847*

Character assigned *Approved* *Good*