

ANNUAL SURVEYS.

13645

No. 3 Survey held at London Date August 24th 30th 1847
 on the City of Hamburgh Master Wade
 Tonnage 379 Built at London When built 1836
 By whom built _____ Owners J. & C. Beattie & Co.
 Port belonging to London Destined Voyage Newcastle
 If Surveyed Afloat or in Dry Dock Duffield Dock approved by the Genl Commr Works

[Signature]
 Recd. 1/1/48

Last Survey, No. 13422 Port of London Classed 12 F. 1

The present Condition of the

Decks <u>good</u>	Treenails <u>apparently good</u>	Windlass and Capstan <u>good</u>
Waterways _____	Breasthooks and Stenson <u>good when seen</u>	Pumps <u>do</u>
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>three do</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings _____	Keelsoles _____	Sails <u>assorted</u>
Plankbeers _____	Clamps and Shells <u>good</u>	Anchor No. of <u>3 B. 12 1/2 K do</u>
Sheerstrakes <u>Caulking laid</u>	Ceiling <u>in fair condition</u>	Cables <u>do</u>
Topsides <u>good for the class</u>	Rudder <u>in good order</u>	Housers and Warps <u>do</u>
Wales _____	Copper <u>2 1/2 in good condition</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>good when seen</u>		

General Observations and Opinion, Has been under examination by the Company's works. Has had a new saddle shaft and a new Reigen Mast & some trifling repairs - She is in efficient condition for the safe conveyance of dry & perishable cargo and may tempo remain as classed -

Committee Minute 3rd Sept 1847
 Character assigned [Signature]
Wm. G. Beattie
[Signature]
 Certificate (if required)

No. 70 Survey held at London Date August 25th 184
 on the County of Bristol Master Stranall
 Tonnage 397 Built at Blackwall When built 1836
 By whom built _____ Owners Genl Commr & Co.
 Port belonging to London Destined Voyage Hamburgh
 If Surveyed Afloat or in Dry Dock Duffield Dock approved by the Genl Commr Works

Last Survey, No. 2056 Port of London Classed 12 A. 1

The present Condition of the

Decks <u>good</u>	Treenails <u>apparently good</u>	Windlass and Capstan <u>in good order</u>
Waterways <u>good</u>	Breasthooks and Stenson <u>good when seen</u>	Pumps <u>in good order</u>
Comings <u>good</u>	Transoms, Pointers, and Crutches <u>good when seen</u>	Boats <u>4 do</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>apparently good</u>
Lower Deck Beams & Fastenings <u>in fair condition</u>	Keelsoles <u>good when seen</u>	Sails <u>one sheet & several sets of yellowed</u>
Plankbeers <u>part caulked</u>	Clamps and Shells <u>good</u>	Anchor No. of <u>3 B. 18 & 18 of several sizes</u>
Sheerstrakes <u>part caulked</u>	Ceiling <u>good</u>	Cables <u>2 barsen do 1/2 inch diam</u>
Topsides <u>part caulked</u>	Rudder <u>in good order</u>	Housers and Warps <u>do</u>
Wales <u>caulked</u>	Copper <u>2 1/2 in good condition</u>	Standing & Running Rigging <u>in good order</u>
Plank (Bottom) and Counter <u>apparently good</u>		

General Observations and Opinion, This vessel's Bottom has been under repair and the hull has been overhauled and some trifling repairs done. She is in good & efficient condition to remain as at present classed.

Committee Minute 3rd Sept 184
 Character assigned [Signature]
Wm. G. Beattie
 Certificate (if required)