

ANNUAL SURVEYS.

13661

No. 380 Survey held at London Date Aug²⁴ 1847
 on the Barque Chopatra Master Mc Cashen
 Tonnage 331 Built at Sancti Spiritus When built 1837
 By whom built Miss Colley & Co Owners Miss Colley & Co
 Port belonging to London Destined Voyage Dominica
 If Surveyed Afloat or in Dry Dock In Cashen's Dry Dock

See to day

Last Survey, No. 1286 Port of London Classed 11 A 1
46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Catches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of <u>2, 2, 1</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Haugers and Warps
Wales	Copper <u>new upon Tell</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done. The Copper Sheathing, stripped off and renewed upon Tell, Caulked from Wales &c. The Foremast, all trunks, four upper Shakes, of Bottom, the Iron Bolts in trunks, of Hold & Ramping, &c. replaced with Bolts of yellow Metal, main Chain Bolts renewed. In Ship of Hull in Starboard & replaced. She is in good condition and appears eligible to remain as Classed A 1

Committee Minute 3 Sept. 1847
 Character assigned 11 A 1 J. Martin
 Certificate (if required)

No. 307 Survey held at London Date Aug²⁰ 1847
 on the Ship "Marlborough" Master J. Webb
 Tonnage 1293 Built at Newcastle When built 1846
 By whom built Miss Smith Owners Miss Smith & Co
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Afloat in East India Dock

Last Survey, No. 3054 Port of Newcastle Classed 12 A 1
46

The present Condition of the

Decks <u>caulked and payed with Marine Glue</u>	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Catches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Haugers and Warps
Wales	Copper <u>Metal 1846</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done. The Seams of masts &c. Caulked and payed with Jeffery's Marine Glue. She appears to be in good condition, entitled to remain as Classed A 1

Committee Minute 3 Sept. 1847
 Character assigned 12 A 1 J. Martin
 Certificate (if required)