

ANNUAL SURVEYS.

13661

No. 580 Survey held at London Date Aug²⁴ 1847
 on the Barque "Chopatra" Master Mc Cashen
 Tonnage 331 Built at Sancti Spiritus When built 1837
 By whom built Miss Colley & Co Owners Miss Colley & Co
 Port belonging to London Destined Voyage Dominica
 If Surveyed Afloat or in Dry Dock In Cashen's Dry Dock

See to day

Last Survey, No. 1286 Port of London Classed 11 A
66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Catches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Haugers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done. The Copper Sheathing, stripped off and renewed upon the hull, caulked from Wales to the keel. The foremast, all the masts, four upper shrouds, of Bottom, the iron bolts in the trunks of hold beams hanging from the main chain bolts, renewed. The ship of Hull in good condition and appears eligible to remain as classed A.

Committee Minute 3 Sept. 1847
 Character assigned 11 A
See Martin
 Certificate (if required)

No. 207 Survey held at London Date Aug²⁰ 1847
 on the Ship "Marlborough" Master J Webb
 Tonnage 1293 Built at Newcastle When built 1846
 By whom built Miss Smith Owners Miss Smith & Co
 Port belonging to London Destined Voyage East India
 If Surveyed Afloat or in Dry Dock Afloat in East India Dock

Last Survey, No. 3054 Port of Newcastle Classed 12 A
66

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Catches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Haugers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done. The seams of weather caulked and payed with Jeffery's Marine Glue. She appears to be in good condition, entitled to remain as classed A.

Committee Minute 3 Sept. 1847
 Character assigned 12 A
See Martin
 Certificate (if required)