

ANNUAL SURVEYS.

12655

No. 192 Survey held at London Date 29th Aug 1847
 on the St. Helen Master Mitchell
 Tonnage 191 Built at Clapton When built 1841
 By whom built _____ Owners Alexander
 Port belonging to Turkey Destined Voyage Calcutta
 If Surveyed Afloat or in Dry Dock Afloat

R. & H. B. 1847

Last Survey, No. 336 Port of Jersey Classed 12 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stewson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>Sound</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>2 B 1 M</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Top-sides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, Is in good and efficient condition and

may remain as classed

J. H. B. 1847

Committee Minute 2nd Sept 1847

Character assigned 12 A 1

Certificate (if required)

No. 36 Survey held at London Date 27 Aug 1847
 on the St. Helena Page Master Page
 Tonnage 118 Built at Sturminster When built 1841
 By whom built _____ Owners Page
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. _____ Port of _____ Classed 9 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stewson _____	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches _____	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame _____	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons _____	Sails <u>do</u>
Planksheers <u>do</u>	Clamps and Shelves _____	Anchors No. of <u>2 B 1 B 1 M</u> <u>do</u>
Sheerstrakes _____	Ceiling _____	Cables <u>do</u>
Top-sides _____	Rudder _____	Hawsers and Warps <u>do</u>
Wales _____	Copper <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion, Is in good and efficient condition

and may remain as classed

J. H. B. 1847

Committee Minute 3rd Sept 1847

Character assigned 9 A 1

Certificate (if required)