

# ANNUAL SURVEYS.

13700

No. 243 Survey held at London Date Sept 13 & 20 1847  
 on the Bk Wilhem Hyde Master McGowan  
 Tonnage 440 Built at Newcastle When built 1841  
 By whom built \_\_\_\_\_ Owners Hyde & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Dry Dock & West India Dock

10. 2. 1. 1847

Last Survey, No. 1253 Port of London

Classed GA1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good &amp; sound</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shells <u>"</u>	Anchors No. of <u>3 Bows 1 Stn 2 Wedges</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow Metal 1845</u>	Standing & Running Rigging <u>good</u>

Plank (Bottom) and Counter

General Observations and Opinion, Metal patches with 30 sheets and 6 keel plates and is in all respects in good & efficient state to return her present class

Committee Minute 21<sup>st</sup> September 1847

Character assigned 9

Certificate (if required)

No. 377 Survey held at London Date Sept 13 & 20 1847  
 on the Bk Columbus Master Dio  
 Tonnage 360 Built at London When built 1845  
 By whom built \_\_\_\_\_ Owners Hall & Co  
 Port belonging to London Destined Voyage \_\_\_\_\_  
 If Surveyed Afloat or in Dry Dock Lincoln Dock & West India Dock

10

Last Survey, No. 13919 Port of London

Classed 10 A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>new lined &amp; overhauled</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>good</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good &amp; sound</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>Good</u>	Clamps and Shells <u>"</u>	Anchors No. of <u>3 Bows 1 Stn 2 Wedges</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Yellow Metal 1845</u>	Standing & Running Rigging <u>good</u>

Plank (Bottom) and Counter good

General Observations and Opinion, Bottom overhauled & patch shes with 13 sheets of metal & new stem plate and is in good condition to continue as classed

Committee Minute 21<sup>st</sup> September 1847

Character assigned 10

Certificate (if required)