

# ANNUAL SURVEYS.

13917

No. 298 Survey held at London Date Dec 13 1847  
 on the SS Gratitude Master Brown  
 Tonnage 271 Built at Farmouth When built 1833  
 By whom built - Owners Lieut  
 Port belonging to London Destined Voyage -  
 If Surveyed Afloat or in Dry Dock on the ways

Last Survey, No. 2242 Port of London Classed 11A1  
C 4

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>from above seen</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 15 1 K</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Smooth</u> <u>do</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion, She is in good and efficient condition fitted with new rigging & may remain as classed  
Jourdan

Committee Minute 24th Dec 1847

Character assigned 12 A 1 JP

Certificate (if required)

No. 124 Survey held at London Date Dec 2 1847  
 on the SS Benjamin Buck Master J. Jeffery  
 Tonnage 528 Built at Corros When built 1846  
 By whom built 543- Owners Blith & Sons  
 Port belonging to London Destined Voyage Mauritius  
 If Surveyed Afloat or in Dry Dock afloat

Last Survey, No. 369 Port of Cones Classed 12A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Secure</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 15 1 K</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	<u>one changed from top to light</u>
Topsides <u>do</u>	Rudder <u>do</u>	Cables <u>do</u>
Wales <u>do</u>	Copper <u>46</u> <u>do</u>	Hawsers and Warps <u>do</u>
Plank (Bottom) and Counter <u>do</u>		Standing & Running Rigging <u>do</u>

General Observations and Opinion, Is in good and efficient condition and may remain as classed  
Jourdan

Committee Minute 24th Dec 1847

Character assigned 12 A 1 JP

Certificate (if required)



© 2019

Lloyd's Register  
Foundation

LON 624-0100



Capstan



© 2019

Lloyd's Register  
Foundation