

ANNUAL SURVEYS.

13946

No. 380 on the *Juliana* Survey held at *London* Date *Nov 5* 184 *7*
 Master *Will*
 Tonnage *238* Built at *Swanmouth* When built *1838*
 By whom built *sub* Owners *Leighs & Co*
 Port belonging to *London* Destined Voyage *-*
 If Surveyed Afloat or in Dry Dock *Afloat*

No 13946

Last Survey, No. *12955* Port of *Southern* Classed *12A1*

The present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>Efficient</i>
Waterways <i>do</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>Same</i>	Timbers of the Frame <i>Good when seen</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>Good</i>	Sails <i>do</i>
Planksheers <i>Good</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>3 B 15 16 do</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>do</i>
Topsides <i>do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>do</i>	Copper <i>46 do</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>		

General Observations and Opinion, *Now hauled around the stanchions & a leak discovered & stopped is in an efficient condition and may remain as classed*

Committee Minute *11th Jan'y* 184 *8*

Character assigned *12A1* *LD*

Certificate (if required)

No. 84 on the *Pasha* Survey held at *London* Date *Dec 18* 184 *7*
 Master *Coggett*
 Tonnage *153* Built at *Swanmouth* When built *1839*
 By whom built *Baxter* Owners *Williams*
 Port belonging to *London* Destined Voyage *-*
 If Surveyed Afloat or in Dry Dock *Wet ways*

Last Survey, No. *11299* Port of *Southern* Classed *12A1*

The present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>Efficient</i>
Waterways <i>do</i>	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings <i>do</i>	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>Same</i>	Timbers of the Frame <i>do</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>do</i>	Sails <i>do</i>
Planksheers <i>Good</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>2 B 15 16 do</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>do</i>
Topsides <i>do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>do</i>	Copper <i>Smooth do</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>		

General Observations and Opinion, *Is in good & efficient condition and may remain as classed*

Committee Minute *11th Jan'y* 184 *8*

Character assigned *12A1* *LD*

Certificate (if required)



© 2019

Lloyd's Register Foundation

LON 624-0129