

ANNUAL SURVEYS.

13948

No. 146 Survey held at London Date Dec^r 13 Jan^y 1848
 on the Bk New Phoenix Master J Barton
 Tonnage 362 Built at Hull When built 1813
 By whom built _____ Owners Thomson & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13353 Port of LondonClassed F, 1

The present Condition of the

| | | |
|---|---|-------------------------------------|
| Decks <u>Good</u> | Treenails <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways <u>"</u> | Breasthooks and Stemson <u>"</u> | Pumps <u>"</u> |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>"</u> | Boats <u>"</u> |
| Upper Deck Beams & Fastenings <u>good for class</u> | Timbers of the Frame <u>"</u> | Masts, Yards, &c. <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Keelsons <u>good</u> | Sails <u>well found</u> |
| Planksheers <u>good for class</u> | Clamps and Shells <u>good for class</u> | Anchors No. of <u>"</u> |
| Sheerstrakes <u>"</u> | Ceiling <u>"</u> | Cables <u>"</u> |
| Topsides <u>"</u> | Rudder <u>good</u> | Hawsers and Warps <u>good</u> |
| Wales <u>good</u> | Copper <u>"</u> | Standing & Running Rigging <u>"</u> |
| Plank (Bottom) and Counter <u>good</u> | | |

General Observations and Opinion, One pair of Iron hanging braces to the hold beam abt the foremast, & caulked from the upper part of the wales to the waterway beam, and is in good condition to
Special Fee 2-2-0
24/1/48
11th Jan 1848
up to the present class F, 1

Committee Minute

Character assigned F, 1

Certificate (if required)

No. 11 Survey held at London Date December 1847
 on the Bk General Sir William Pitt Master Outenburg
 Tonnage 371 Built at Swansea When built 1845
 By whom built _____ Owners Richardson
 Port belonging to Swansea Destined Voyage Cuba
 If Surveyed Afloat or in Dry Dock Weymouth Dock

Last Survey, No. 201 Port of SwanseaClassed GA1

The present Condition of the

| | | |
|---|--|--|
| Decks <u>Good</u> | Treenails <u>good</u> | Windlass and Capstan <u>good</u> |
| Waterways <u>"</u> | Breasthooks and Stemson <u>"</u> | Pumps <u>"</u> |
| Comings <u>"</u> | Transoms, Pointers, and Crutches <u>"</u> | Boats <u>"</u> |
| Upper Deck Beams & Fastenings <u>good</u> | Timbers of the Frame <u>sound where seen</u> | Masts, Yards, &c. <u>"</u> |
| Lower Deck Beams & Fastenings <u>"</u> | Keelsons <u>good</u> | Sails <u>well found</u> |
| Planksheers <u>"</u> | Clamps and Shells <u>"</u> | Anchors No. of <u>3 Bows 1 Stern 2 Hinge</u> |
| Sheerstrakes <u>"</u> | Ceiling <u>"</u> | Cables <u>well found</u> |
| Topsides <u>"</u> | Rudder <u>"</u> | Hawsers and Warps <u>"</u> |
| Wales <u>"</u> | Copper <u>yellow metal over felt</u> | Standing & Running Rigging <u>good</u> |
| Plank (Bottom) and Counter <u>"</u> | | |

General Observations and Opinion, Bottom caulked & sheathed with yellow metal over felt & platform fitted to carry copper ore, is in good condition to continue as classed

Committee Minute

Character assigned G, 1

© 2019

Lloyd's Register
Foundation

Certificate (if required)