

ANNUAL SURVEYS.

No. 182 Survey held at Sunder Date Jan^y 26 1848
 on the Bk Castle Larchlan Master Bourne
 Tonnage 435 Built at Greenock When built 1841
 By whom built _____ Owners Dawson
 Port belonging to Sunder Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. 1356 Port of Sunder

Classed A. 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>sound when seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Buoys 1 5/8 in 2 1/2 in</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>45</u>	Standing & Running Rigging <u>good & firm</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Two Foremast & Mainmast, and is in good condition for the
safe conveyance of passengers & cargo to all parts
of the world and may continue as classed

Committee Minute 1st Feb^y 1848

Character assigned A. 1

Certificate (if required)

No. 14 Survey held at Sunder Date Jan^y 26 1848
 on the Ship Coramandel Master J. Gray
 Tonnage 660 Built at Greenock When built 1843
 By whom built _____ Owners J. J. Campbell
 Port belonging to Glasgow Destined Voyage Cape & Bombay
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13007 Port of Sunder

Classed 12 A 1

The present Condition of the


Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound when seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Buoys 1 5/8 in 2 1/2 in</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>45</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Has been in dry dock & bottom examined, Copper patched
about 20 sheets, presents a very firm appearance &
may retain her present character

Committee Minute 1st Feb^y 1848

Character assigned 12 A 1

Certificate (if required)



© 2019

Lloyd's Register Foundation

LON624-0185