

ANNUAL SURVEYS.

14002

No. 380 Survey held at London Date Janth 24th Feb 2 1848
 on the Bk Sir Chas Napier Master Pemberton
 Tonnage 509 Built at Mianmachi When built 1841
 By whom built _____ Owners Sang
 Port belonging to Greenock Destined Voyage New Orleans
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 2090 Port of Glyde 1845 Classed A, 1 S S 4 years

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & sound</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>44</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Has been in dry dock & had the Copper fastened and at the present time the lower breasthooks partially decayed one of them has been placed over each and some better compensating their deficiency and we are of opinion she may retain her present class A, 1

Committee Minute 3 Feb 1848

Character assigned Special 2. 2. 0

Certificate (if required)

No. 491 Survey held at London Date Jan^{ry} 1848
 on the Bk Buckers Master Neilson
 Tonnage 396 Built at London When built 1829
 By whom built _____ Owners Buckers
 Port belonging to London Destined Voyage St Vincent
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13506 Port of London Restored 1841 Classed A, 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & sound</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>well found</u>
Wales <u>"</u>	Copper <u>47</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Is in a very efficient state & may retain her present class

Committee Minute 1st Feb 1848

Character assigned Spec 2. 2. 0

Certificate (if required)



© 2019

Lloyd's Register Foundation

1810-429107