

REPORT of SURVEY for REPAIRS.

No. 461 Survey held at London Date 17th Feb^r 1848
 on the B^y "Circassian" Master Cripps Hall
 Tonnage 202 Built at Wexham When built 1835
 By whom built _____ Owners Hall & Co
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in New Crane Dock

Last Survey, No. 12417

Port London

Classed 10 A
1845 Cont^d 3 1/2 A

REPAIRS

at present bottom stripped hung in Shores Caulked
 to wales and treeped with Yellow Metal on
 double Paper - New Catheads and Carbons Rouse Pipe
 Rudder bands refastened -

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

This Vessel is in efficient Condition
 and may remain as classed

The Amount of Fee.....£..... is received by me,

Certificate (if required).....

Committee's Minute 25th Feb^r 1848

Character assigned Class 3 A

Special Damage £2.2



© 2019

Lloyd's Register
 Foundation

Lon 624-0243