

REPORT of SURVEY for REPAIRS.

Change of Owners

No. 903 Survey held at London Date March 27 1848
 on the Bk Ava Master Webster
 Tonnage 460 Built at New Brunswick When built 1833
 By whom built _____ Owners P Webster
 Port belonging to Wm. H. Scarbro Destined Voyage Duquesne
 If Surveyed Afloat or in Dry Dock Plade Dock

Last Survey, No. 1326 1844 Classed E. 1 S. S. 44
 Port London

REPAIRS Hang of the bottom caulked, One pair of staple standards aboast of the mainmast, one pair of Iron hanging benches to the foremast Deck beam, & a pair of Iron riders aft over the Port timbers

Present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good in place</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well frayed</u>
Planksheers <u>"</u>	Clamps and Shells <u>"</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, In good condition for the safe conveyance of dry and perishable cargoes and may continue as classed

W. M. Webster

The Amount of Fee.....£ 2 : — : — is received by me, W. M. Webster

Certificate (if required) _____

Committee's Minute 11th April 1848

Character assigned W. M. Webster

Brookland



© 2019

Lloyd's Register
Foundation

LON 624-0377