

# ANNUAL SURVEYS.

No. 68 Survey held at London Date May 20 1847  
 on the General Palmer Master Seaton  
 Tonnage 552 Built at Calcutta When built 1816  
 By whom built                      Owners Sy F. Jones  
 Port belonging to London Destined Voyage Hudson's Bay  
 If Surveyed Afloat or in Dry Dock In Carters Dry Dock

Last Survey, No. 13911 Port of London Classed 2A 1  
4/

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper Metal When put on <u>46</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, F & Dpt 25 p 33

Now done See keelsons fitted to Bows for her present Voyage extending from middle of Wales down to about two feet below light water mark, and lengthwise about 25 feet from the stem; Waterway and Stanchion Deck mgt. it Caulked. She appears to be in good condition.

Committee Minute 26th May 1847 for the safe conveyance of Dry and perishable Charges to and from all parts of the world, eligible to remain as Classed 2A 1  
 Character assigned 2A 1 J. S. Martin  
 Certificate (if required)

No. 34 Survey held at London Date May 16 1847  
 on the Ship "Barham" Master Gimblett  
 Tonnage 1149 Built at London When built 1846  
 By whom built Green Owners Green  
 Port belonging to London Destined Voyage Calcutta  
 If Surveyed Afloat or in Dry Dock In East India Dock, Afloat.

Last Survey, No. 12770 Port of London Classed 12A 1  
46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shells	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper Metal When put on <u>46</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion,

She has been in Dry Dock to examine Bottom, the Wales, Upper and Lower Decks Caulked.

She is in good condition eligible to remain as Classed 2A 1

Committee Minute 26th May 1847

Character assigned 12A 1

© 2019  
 Lloyd's Register  
 Foundation  
 Certificate (if required)