

ANNUAL SURVEYS.

14325

No. 63 Survey held at London Date 26th May 2nd Ann 1848
 on the Bk "Indian Chief" Master Noble
 Tonnage 349 Built at Sunderland When built 1846
 By whom built Wemyss Owners Wemyss
 Port belonging to Trusburgh Destined Voyage Trusburgh
 If Surveyed Afloat or in Dry Dock in Globe Dock & St Kilda Dock

Last Survey, No. 2938 Port of Sunderland Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>overhauled Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>—</u>	Breasthooks and Stemson <u>—</u>	Pumps <u>—</u>
Comings <u>—</u>	Transoms, Pointers, and Crutches <u>—</u>	Boats <u>Three</u>
Upper Deck Beams & Fastenings <u>—</u>	Timbers of the Frame <u>—</u>	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>—</u>	Keelsons <u>—</u>	Sails <u>24 cuts</u>
Planksheers <u>—</u>	Clamps and Shelves <u>—</u>	Anchors No. of <u>3. 1. 1</u>
Sheerstrakes <u>Caulked</u>	Ceiling <u>—</u>	Cables <u>Sufficient</u>
Topsides <u>—</u>	Rudder <u>—</u>	Hawsers and Warps <u>D</u>
Wales <u>—</u>	Copper <u>4 Metal new</u>	Standing & Running Rigging <u>D</u>
Plank (Bottom) and Counter <u>—</u>	<u>for paper May 1848</u>	

General Observations and Opinion,

at present bottom stripped Caulked and trenched with yellow metal on paper several treenails drawn out for inspection and found sound wales topsides and sheerstrakes Caulked & in efficient condition and may be repaired

Committee Minute

Character assigned

10 A 1 Clipped Stitcher
Circled for Stitcher
 Certificate (if required)

No. 10 Survey held at London Date May 31st 1848
 on the Bk "Cairo" Master Hogg
 Tonnage 300 Built at Dundee When built 1839
 By whom built — Owners Jones & Co
 Port belonging to London Destined Voyage Jamaica
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13952 Port of London 1047 Classed 9 A 1

The present Condition of the

Decks <u>good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound where seen</u>	Masts, Yards, &c. <u>new mizen mast</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bows 1 str 2 Hodge</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>"</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>—</u>		

General Observations and Opinion,

I am of opinion this vessel is in good condition & when repaired will be

Committee Minute

Character assigned

6th June 1848
9 A 1 Stitcher
Circled for Stitcher
 Certificate (if required)



Lloyd's Register
 Foundation