

REPORT of SURVEY for REPAIRS.

Change of Names

No. 470 Survey held at London Date June 20/21 1849
 on the Brig "Mary Ann" Master J. Harrison
 Tonnage 197 Built at Sunderland When built 1841
 By whom built James Thompson Owners Miss Thompson
 Port belonging to Whitby Destined Voyage Dantzic
 If Surveyed Afloat or in Dry Dock On Captain's Mays

Last Survey, No. 28 Classed 6 A 1
 Port Sunderland 6 mo 4 y

REPAIRS

At the present time. Topsides and Sheer Strakes
 Caulked; about 50 Treennails in d^o renewed, the
 Iron Tank in Run removed and the Ceiling slightly
 repaired there, a few of the Hold Beam Hanging
 Knee Bolts replaced.

Present Condition of the

| | | | | | |
|-------------------------------|-----------------------|----------------------------------|--|----------------------------|---|
| Decks | } <u>good</u> | Treenails | | Windlass and Capstan | |
| Waterways | | Breasthooks and Stemson | } <u>good when seen</u> | Pumps | |
| Comings | | Transoms, Pointers, and Chatches | | Boats | |
| Upper Deck Beams & Fastenings | } <u>as when seen</u> | Timbers of the Frame | | Masts, Yards, &c. | } <u>In good order</u> <u>and sufficient</u> |
| Lower Deck Beams & Fastenings | | Keelsons | | Sails | |
| Planksheers | | Clamps and Shelves | | Anchors No. of | |
| Sheerstrakes | <u>d^o</u> | Ceiling | <u>d^o</u> | Cables | |
| Topsides | <u>d^o</u> | Rudder | <u>d^o</u> | Hawsers and Warps | |
| Wales | <u>d^o</u> | Copper | <u>By Metal 1 m. 4 y d^o</u> | Standing & Running Rigging | |
| Plank (Bottom) and Counter | <u>d^o</u> | | | | |

General Observations and Opinion.

*This Brig appears to be in good condition
 eligible to remain as Classed A 1*

The Amount of Fee.....£ 1 : : is received by me, J. Martin

Certificate (if required) : 5 :

Committee's Minute 23rd June 1848

Character assigned A 1

For fee extra attendance £1-1-0



© 2019

Lloyd's Register
 Foundation