

Change of Prms 14370

REPORT of SURVEY for REPAIRS.

No. 19 Survey held at London Date June 5th 1848
 on the Ship "Ratcliff" Master Philipson
 Tonnage 739 Built at Whitby When built 1842
 By whom built _____ Owners Finlay
 Port belonging to London Destined Voyage to Cape Good Hope
 If Surveyed Afloat or in Dry Dock afloat, had been docked

Rec'd 10 June

Last Survey, No. 12810 Classed 11 A 1

Port London
 REPAIRS was scraped from the copper on and found good
few biscuits driven out and found good upper works
caulked,

Present Condition of the

Decks	<u>good</u>	Treenails	<u>good</u>	Windlass and Copstan	<u>efficient</u>
Waterways	<u>do</u>	Breasthooks and Stemson	<u>do</u>	Pumps	<u>do</u>
Comings	<u>do</u>	Transoms, Pointers, and Crutches	<u>do</u>	Boats	<u>do</u>
Upper Deck Beams & Fastenings	<u>sound</u>	Timbers of the Frame	<u>good / cut for</u>	Masts, Yards, &c.	<u>do</u>
Lower Deck Beams & Fastenings	<u>do</u>	Keelsons	<u>good</u>	Sails	<u>do</u>
Planksheers	<u>good</u>	Clamps and Shelves	<u>do</u>	Anchors No. of	<u>3 A 15 11 do</u>
Sheerstrakes	<u>do</u>	Ceiling	<u>do</u>	Cables	<u>do</u>
Topsides	<u>do</u>	Rudder	<u>do</u>	Hawsers and Warps	<u>do</u>
Wales	<u>do</u>	Copper	<u>do</u>	Standing & Running Rigging	<u>do</u>
Plank (Bottom) and Counter	<u>do</u>				

General Observations and Opinion,
Is in good and efficient condition
and may remain as classed

Philipson

The Amount of Fee.....£ 3 : - : - is received by me,

Certificate (if required) : 10 :-

Committee's Minute 30th June 1848

Character assigned 11 A 1
Philipson



© 2019
 Lloyd's Register
 Foundation
 LON 625-0079