

REPORT of SURVEY for REPAIRS.

No. 10007 Survey held at London Date July 20 1848
 on the Active Master W. J. Hall
 Tonnage 71 Built at Widbridge When built 1839
 By whom built _____ Owners Cheese J.
 Port belonging to London Destined Voyage Leam
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 10007 Classed 12A1

Port London

REPAIRS In June last at Leam had new deck of Red Pine & caulked

Present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clumps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>stated to be put on in 1846</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion. This vessel had cargo in the after hold and could not see the after part of the keelson, but when seen is in a very efficient state and fit to retain her present class,

The Amount of Fee.....£ — : 10 : — is received by me. W. J. Hall

Certificate (if required)

Committee's Minute 28th July 1848

Character assigned 12 A 1



© 2019

Lloyd's Register Foundation

LON 625-0137