

REPORT of SURVEY for REPAIRS.

14486

No. 285 on the Ship "Boyne" Survey held at London Date 18th July 1848
 Tonnage 620 Built at Calcutta Master A. Vincent
 By whom built Owners Phillipps & Co
 Port belonging to London Destined Voyage to India
 If Surveyed Afloat or in Dry Dock in Shrocks Dock

Last Survey, No. 13638 Classed *A. 1
 Port London

REPAIRS at present bottom Caulked to the Wales & yellow Metal on Paper - two new Iron Crutches fitted to Wood Joist - Top gallant fore Castle Deck now lengthened all new beams & edges of Plank sheer the waterways and Skelf of East India Deck 2 Pairs of hanging Knees to fore castle - New Capstand fitted Deck and waterways Caulked - Hull Masts and Rigging generally overhauled & refitted -

Present Condition of the

Decks	Treenails	Windlass and Capstan new
Waterways	Breasthooks and Stemson	Pumps good
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. Sufficient
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	Good	

General Observations and Opinion

This Vessel is in efficient Condition and in our opinion fit for the safe conveyance of dry and perishable Cargoes to & from all parts of the World and may remain Clapped

The Amount of Fee £ 3 : - is received by me, and may remain Clapped

Certificate (if required) : 10. -

Committee's Minute 15th Aug. 1848

Character assigned