

ANNUAL SURVEYS.

14483

No. 13 Survey held at London Date August 12 1848
 on the Ship St. Andrew Master S. L. ...
 Tonnage 499 Built at Glasgow When built 1845
 By whom built ... Owners Pickens & Co.
 Port belonging to Dublin Destined Voyage Dublin
 If Surveyed Afloat or in Dry Dock Afloat

No. 14 Aug

Last Survey, No. 12202 Port of London 1847 Classed 11A1

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	<u>good</u>	Boats	"
Upper Deck Beams & Fastenings	"	Timbers of the Frame	<u>good</u>	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	<u>Good</u>	Sails	<u>well found</u>
Planksheers	"	Clamps and Shelves	"	Anchors	No. of <u>3 B^d 1 Stn 2 Wedges</u>
Sheersirakes	"	Ceiling	"	Cables	<u>well found</u>
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	When put on <u>1847</u>	Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter	"				

General Observations and Opinion, Appears in all respects in a good & efficient state to retain her present class to continue as classed

M. W. ...

Committee Minute 15th Aug 1848

Character assigned 10 A

Certificate (if required)

No. 4 Survey held at London Date Aug 12 1848
 on the Ship By Jubber Master T. Smith
 Tonnage 224 Built at Scarbree When built 1832
 By whom built ... Owners Sindell & Co.
 Port belonging to Scarbree Destined Voyage Demesara
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. ... Port of London 1847 Classed F. 11 B 11 A 1

The present Condition of the

Decks	<u>Good</u>	Treenails	<u>good</u>	Windlass and Capstan	<u>good</u>
Waterways	"	Breasthooks and Stenson	"	Pumps	"
Comings	"	Transoms, Pointers, and Crutches	"	Boats	"
Upper Deck Beams & Fastenings	<u>good</u>	Timbers of the Frame	<u>good</u>	Masts, Yards, &c.	"
Lower Deck Beams & Fastenings	"	Keelsons	<u>Good</u>	Sails	<u>well found</u>
Planksheers	<u>good</u>	Clamps and Shelves	"	Anchors	No. of <u>3 B^d 1 Stn 1 Wedge</u>
Sheerstrakes	"	Ceiling	"	Cables	<u>well found</u>
Topsides	"	Rudder	"	Hawsers and Warps	"
Wales	"	Copper	When put on <u>1846</u>	Standing & Running Rigging	<u>good</u>
Plank (Bottom) and Counter	<u>good</u>				

General Observations and Opinion, Am of opinion this is in a good & efficient state for the safe conveyance of dry goods to the Cape & from all parts of the world & may continue as classed

M. W. ...

Committee Minute 15th Aug 1848

Character assigned 10 A

Certificate (if required)

