

REPORT of SURVEY for REPAIRS.

No. 498 Survey held at London Date July & Aug 1848
 on the Ship "Ann" Master Stimson
 Tonnage 665 Built at Palovina When built 1815
 By whom built — Owners Mannings & Co
 Port belonging to London Destined Voyage —
 If Surveyed Afloat or in Dry Dock Dry Dock & London Dock
d. 22nd 42 1/2 m 46 Sept 42 1/2 m 46

Last Survey, No. 13043 Port London Classed —

REPAIRS As the present time one new length of sheer blocks
on each side fore part of upper deck doweled

with 2 inch dougls properly nailed 1/4" under

Surveyed in conformity with the Society's Rules
sections 54th scraped bright from the copper up

The main deck planks the bolts of all
the knees, the planks strong to which they pass, the
plank sheers & waterways the beams, narrow timbers
knights heads breast boards, transoms, the floors
and keelsons, the plankway outside from the upper
up the ceiling the frame and inner surface of the
outer side planks, all in good condition the keel is

Present Condition of the straight and general form unaltered

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Plank sheers	Clamps and Shells	Anchors No. of <u>3 B 1 S 14</u>
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>good</u> When put on <u>at</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, She is in good and efficient condition
fit for the conveyance of dry and perishable
cargoes to & from all parts of the world and
may be recaptured

The Amount of Fee £ 3 : : 0 is received by me.

Special 3 : 3 : 0

Certificate (if required) 10 :

Committee's Minute 24 Aug 1848

Character assigned —

