

14528

REPORT of SURVEY for REPAIRS.

Reclapping

[Signature]

Recd 24 Aug

No. *150* Survey held at *London* Date *15 Aug* 184*8*
on the Ship *"Carshalton Park"* Master _____
Tonnage *441* Built at *Southampton* When built *1811*
By whom built _____ Owners *Carter*
Port belonging to *London* Destined Voyage _____
If Surveyed Afloat or in Dry Dock *in Same Kilda Slip*
E & d. *34* M. *1 m 46* Dips & Sips *46*

Last Survey, No. *12460* Port *London* Classed *R. & expunged*

REPAIRS *at Present Ceiling dubbed over and repaired.*
in hold yellow metal galvanized and repaired
upper works overhauled & caulking searched

Present Condition of the

Decks	Treenails	Windlass and Capstan	<i>Good</i>
Waterways	Breasthooks and Stemson	Pumps	<i>—</i>
Comings	Transoms, Pointers, and Crutches	Boats	<i>four</i>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.	<i>Sufficient</i>
Lower Deck Beams & Fastenings	Keelsons	Sails	<i>on</i>
Planksheers	Clamps and Shelves	Anchors No. of	<i>3 1 2</i>
Sheerstrakes	Ceiling	Cables	<i>Sufficient</i>
Topsides	Rudder	Hawsers and Warps	<i>on</i>
Wales	Copper	Standing & Running Rigging	<i>on</i>
Plank (Bottom) and Counter	When put on		

General Observations and Opinion,

This Vessel is in efficient Condition and in my opinion fit for the safe conveyance of heavy & perishable Cargoes and may be

The Amount of Fee.....£ *1* : — : is received by me *Clapton*
Special..... : — :
[Signature]

Certificate (if required) : *10* : — : *[Signature]*

Committee's Minute *11 Sept 1848*
Character assigned *Fit for service*
[Signature]