

ANNUAL SURVEYS.

14742

No. 346 Survey held at London Date Nov 22 1848
 on the Bk Spartan Master J. Paine
 Tonnage 364 Built at Chelston When built 1825
 By whom built _____ Owners G. Marshall
 Port belonging to London Destined Voyage Udelaine
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13629 Port of London Classed A. 1 Robert

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 B^{ns} 1 Str. 2 Hedges</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>47</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, At the present time two new deck beams & one new
has been in dry dock arr. to a hot beam & 4 pairs of additional iron
bottom examined hanging knees to the hot beams, from the good
and efficient condition am of opinion she is fit for the
safe conveyance of dry & perishable cargoes to & from all
24th Nov 1848 parts of the world & may continue as classed
 Committee Minute _____
 Character assigned A. 1 Robert

Certificate (if required)

No. 213 Survey held at London Date Nov 22 1848
 on the Bk Blanche Master Abrams
 Tonnage 319 Built at Sunderland When built 1845
 By whom built _____ Owners Thompson
 Port belonging to London Destined Voyage Demerara
 If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 13657 Port of London Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan _____
Waterways <u>"</u>	Breasthooks and Stenson <u>"</u>	Pumps _____
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats _____
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good</u>	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails _____
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of _____
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables _____
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps _____
Wales <u>"</u>	Copper <u>Yellow Metal over felt</u>	Standing & Running Rigging _____
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, Has been in dry dock & bottom caulked & sheathed
with yellow metal over felt and is in a good & efficient
state to continue in her present class

Committee Minute 29th Nov 1848
 Character assigned 10 A 1

Certificate (if required)