

# ANNUAL SURVEYS.

No. 535 Survey held at London Date Dec 23 25 18 48  
on the "Columbus" Master Edie  
Tonnage 454 Built at Sunderland When built 1845  
By whom built None Owners W. & A.  
Port belonging to London Destined Voyage Calcutta  
If Surveyed Afloat or in Dry Dock Flores DK

Last Survey, No. 13700 Port of London Classed 10A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 B 15 1/2 H do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Ym</u> When put on <u>Dec 1848</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Shipped Caulked and Sheerstrakes with yellow Metal is in an efficient Condition and may remain as Classed.

Committee Minute 19th Jan 1849

Character assigned 10A1

Special 2.2  
Condition

Certificate (if required)

No. 844 Survey held at London Date Jan 4 15 18 49  
on the "Cable" Master Green  
Tonnage 334 Built at Murm When built 1841  
By whom built None Owners Collins  
Port belonging to London Destined Voyage Dumfries  
If Surveyed Afloat or in Dry Dock afloat had been dry dock

Last Survey, No. 14079 Port of London Classed 5A1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>do</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>do</u> When put on <u>47</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Is in good and efficient Condition and may remain as Classed

Committee Minute 19th Jan 1849

Character assigned 5A1

Special 2.2  
Condition

© 2019

Lloyd's Register

Certificate (if required)