

No. 246

on the

Survey held at London

Date

Feb^r 10th 19th 1849Tonnage 102Built at Rye

Master

Catchpole

By whom built

Owners

When built 1841

Port belonging to

London

Destined Voyage

Copenhagen

If Surveyed Afloat or in Dry Dock

In Hawk's Dry DockLast Survey, No. 13132 Port ofLondon

Classed

12 A

The present Condition of the

Decks

Waterways

Comings

Upper Deck Beams & Fastenings

Lower Deck Beams & Fastenings

Planksheers

Sheerstrakes

Topsides

Wales

Plank (Bottom) and Counter

Treenails

Breasthooks and Stemson

Transoms, Pointers, and Crutches good when seen

Timbers of the Frame

Keelsons not seen for

Ballast

Clamps and Shelves

Ceiling

Rudder

Copper Yellow MetalWhen put on new new

Windlass and Capstan

Pumps

Boats

Masts, Yards, &c.

Sails

Anchors No. of

Cables

Hawsers and Warps

Standing & Running Rigging

General Observations and Opinion,

Now done. Wales, Topsides, and Sheerstrakes scraped bright. Copper Sheathing stripped off hung in Shores. Caulked from upper edge of Wales to Keel and the Bottom sheathed with Yellow Metal upon Paper.

Committee Minute

23rd Feb 1849

Character assigned

12 A

She appears to be in good condition, fit to remain as Classed.