

ANNUAL SURVEYS.

No. 346 Survey held at London Date March 9 1849
 on the My Brilliant Master Furlong
 Tonnage 240 Built at Workington When built 1818
 By whom built — Owners Mr. A. A. A.
 Port belonging to Workington Destined Voyage Somerset
 If Surveyed Afloat or in Dry Dock afloat has been upon the voyage

Last Survey, No. 14209 Port of London Classed A.1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>30/15/10</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>—</u> When put on <u>—</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

She is in good and efficient condition fit for the conveyance of any and every kind of cargo and may remain as classed A.1.

Committee Minute 13th March 1849

Character assigned A.1

Certificate (if required)

No. 229 Survey held at London Date Feb 23 1849
 on the My "Chance" Master Wrayles
 Tonnage 328 Built at Sunderland When built 1842
 By whom built — Owners Mr. A. A. A.
 Port belonging to London Destined Voyage California
 If Surveyed Afloat or in Dry Dock Limbedu Ship

Last Survey, No. 19907 Port of London Classed A.1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Sound</u>	Timbers of the Frame <u>Good when seen</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>Good</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>30/15/10</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>—</u> When put on <u>—</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

Generally overhauled is in good and efficient condition and may remain as classed A.1.

Committee Minute 13th March 1849

Character assigned A.1

© 2019

Lloyd's Register
Foundation