

ANNUAL SURVEYS.

15091

No. 161 Survey held at London Date April 7th 1849
 on the Steam Vessel Penzance Master Wendell
 Tonnage 202 Built at Greenock When built 1840
 By whom built _____ Owners Genl Steam Navigation Company
 Port belonging to London Destined Voyage Harve
 If Surveyed Afloat or in Dry Dock Afloat 160 Horse Power
PTND & S.P.R. 42 D.P. 43

Last Survey, No. 12662 Port of London

Classed 7A 1 mro E
expunged

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson <u>good</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame <u>sound & new</u>	Masts, Yards, &c. <u>good</u>
Lower Deck Beams & Fastenings	Keelsons <u>good</u>	Sails
Planksheers <u>Good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes	Ceiling <u>"</u>	Cables
Topsides	Rudder <u>"</u>	Hawsers and Warps
Wales	Copper <u>1840</u> When put on <u>in Oct</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, In Oct last caulked & a general overhaul
is in good condition for the safe conveyance of dry
& perishable cargoes and may continue as above
Fee £ 10. Paid

Committee Minute 13th April 1849

Character assigned 1st

Certificate (if required)

No. 472 Survey held at London Date April 11th 1849
 on the By Harve Master Brace
 Tonnage 145 Built at Humberland When built 1835
 By whom built _____ Owners Perkins
 Port belonging to London Destined Voyage Bordeaux
 If Surveyed Afloat or in Dry Dock On the Harve

Last Survey, No. 12698 Port of London

Classed 4A

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>sound & new</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>sufficient</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps
Wales <u>"</u>	Copper _____ When put on _____	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Bottom examined & caulked, and is in good condition to
continue as above

Committee Minute 13th April 1849

Character assigned 1st

Certificate (if required)



© 2019

Lloyd's Register
Foundation