

ANNUAL SURVEYS.

15160

No. ⁴⁴⁸ Survey held at London Date May 15 1849
 on the Brig "Mary Ann" Master J. Gay
 Tonnage 201 Built at Ipswich When built 1830
 By whom built _____ Owners J. Crisp
 Port belonging to London Destined Voyage Algoa Bay
 If Surveyed Afloat or in Dry Dock On Crisp & Sons Mays

Recd 15 May

Last Survey, No. 14398 Port of London Classed 12 A 1
40

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good where seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order and sufficient</u>
Lower Deck Beams & Fastenings <u>d^o where seen</u>	Keelsons <u>d^o</u>	Sails
Planksheers	Clamps and Shelves <u>d^o</u>	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>Yellow Metal</u> When put on <u>45</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>	<u>Repaired</u>	

General Observations and Opinion,

now done. The Yellow Metal Sheathing heavily repaired

Committee Minute 18th May 1849 She appears to be in good condition eligible to remain as Classed A 1
 Character assigned 12 A 1 J. S. Martin
 Certificate (if required)

No. ^{Supp} Survey held at London Date May 11 1849
 on the Brig "Cleopatra" Master J. Love
 Tonnage 157 1/2 Built at P.R. Island When built 1840
 By whom built _____ Owners H.H. Lindsay
 Port belonging to London Destined Voyage Cape of G. Hope
 If Surveyed Afloat or in Dry Dock In Port & aft Dry Dock

Last Survey, No. 14406 Port of London Classed 4 A 1
40

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good where seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order and sufficient</u>
Lower Deck Beams & Fastenings <u>d^o where seen</u>	Keelsons <u>d^o</u>	Sails
Planksheers	Clamps and Shelves <u>d^o</u>	Anchors No. of
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>Yellow Metal</u> When put on <u>40</u>	Standing & Running Rigging
Plank (Bottom) and Counter <u>d^o</u>	<u>F.S.</u>	

General Observations and Opinion,

Now done A Listing of Y Metal and Wood Sheathing cut out at Keel Seam to find a Leak, which is stated to be found and stopped. Wales and Topsides scraped bright and repulked. She appears eligible to remain as Classed A 1

Committee Minute 18th May 1849 She appears eligible to remain as Classed A 1
 Character assigned 4 A 1 J. S. Martin
 Certificate (if required)