

ANNUAL SURVEYS.

15238

No. 137 Survey held at London Date May 30 Jun 2 1849
 on the Wilberforce B^d Master Deuby
 Tonnage 165 Built at Poole When built 1825
 By whom built _____ Owners Deuby
 Port belonging to Easton Destined Voyage Bahamas
 If Surveyed Afloat or in Dry Dock West India Dock

R 220 June

Last Survey, No. 1411 Port of London Classed *A1

The present Condition of the

Decks <u>good</u>	Treenails <u>apparently good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson <u>good</u>	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>in good condition</u>
Lower Deck Beams & Fastenings _____	Keelsons <u>good</u>	Sails <u>cut</u>
Planksheers <u>good</u>	Clamps and Shelves _____	Anchors No. of <u>sufficient in</u>
Sheerstrakes _____	Ceiling _____	Cables <u>quantity</u>
Topsides _____	Rudder <u>in good order</u>	Hawsers and Warps _____
Wales _____	Copper <u>19 lbs</u> When put on <u>1848</u>	Standing & Running Rigging _____

General Observations and Opinion,

Notice was given to the Owner of this vessel to submit her to the Survey 54 & 60 under an idea that she had not under gone it. She had however gone through it in 1848 & the bottom was in consequence with drawn - she is in good condition to remain as at present classed

Committee Minute 26th June 1849 *Accepted & approved*
 Character assigned By J. A. ...

Certificate (if required)

No. 491 Survey held at London Date May 29th Jun 2nd 1849
 on the Gleopatra B^d Master M^r Latham
 Tonnage 368 Built at London When built 1837
 By whom built _____ Owners Culling & Co
 Port belonging to London Destined Voyage Dumfries
 If Surveyed Afloat or in Dry Dock Swiss Rive Ship & West India Dock

Last Survey, No. 14719 Port of London Classed 1/A1

The present Condition of the

Decks <u>good</u>	Treenails <u>apparently good</u>	Windlass and Capstan _____
Waterways _____	Breasthooks and Stenson <u>good</u>	Pumps _____
Comings _____	Transoms, Pointers, and Crutches <u>good</u>	Boats _____
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good when seen</u>	Masts, Yards, &c. <u>in good order and</u>
Lower Deck Beams & Fastenings _____	Keelsons <u>good</u>	Sails <u>condition & sufficient</u>
Planksheers <u>good</u>	Clamps and Shelves _____	Anchors No. of <u>in quantity</u>
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder <u>in good order</u>	Hawsers and Warps _____
Wales <u>2 starb shafts part new</u>	Copper <u>C on fore</u> When put on <u>47</u>	Standing & Running Rigging <u>handed</u>

General Observations and Opinion,

This vessel has had her bottom examined and copper repaired, she is in good condition to remain as at present classed.

Committee Minute 26th June 1849 *Accepted & approved*
 Character assigned Class 4 B

