

Change of owners 15332

REPORT of SURVEY for REPAIRS.

No. ⁴⁹¹ Survey held at London Date June 28th 1849
on the "Lydford" Master _____
Tonnage 313 Built at Shields When built 1840
By whom built _____ Owners Carter
Port belonging to London Destined Voyage West India
If Surveyed Afloat or in Dry Dock W. I. Dock

Last Survey, No. 13867 Port London Classed 10A1

REPAIRS

Present Condition of the

Decks <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>efficient</u>
Waterways <u>do</u>	Breasthooks and Stemson <u>do</u>	Pumps <u>do</u>
Comings <u>do</u>	Transoms, Pointers, and Crutches <u>do</u>	Boats <u>do</u>
Upper Deck Beams & Fastenings <u>Same</u>	Timbers of the Frame <u>Good</u> <u>do</u>	Masts, Yards, &c. <u>do</u>
Lower Deck Beams & Fastenings <u>do</u>	Keelsons <u>do</u>	Sails <u>do</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>do</u>	Anchors No. of <u>3 AIS/H</u> <u>do</u>
Sheerstrakes <u>do</u>	Ceiling <u>do</u>	Cables <u>do</u>
Topsides <u>do</u>	Rudder <u>do</u>	Hawsers and Warps <u>do</u>
Wales <u>do</u>	Copper <u>Metel</u> When put on <u>1847</u>	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter <u>do</u>		

General Observations and Opinion,

She is in good efficient condition and slight
to remain as classed

The Amount of Fee.....£ 2 : - : - is received by me, H

Special..... : :

Certificate (if required) : :

Committee's Minute 3rd Aug 1849

Character assigned 10A1



© 2019

Lloyd's Register
Foundation

LON 627-0052