

# ANNUAL SURVEYS.

15302

No. 121 Survey held at London Date Aug 10<sup>th</sup> 11 1849  
 on the 13<sup>th</sup> Prince of Wales Master Alexander  
 Tonnage 516 Built at Aberdeen When built 1842  
 By whom built \_\_\_\_\_ Owners Thompson jun<sup>r</sup>  
 Port belonging to Aberdeen Destined Voyage South America  
 If Surveyed Afloat or in Dry Dock In Lavender Dry Dock

Last Survey, No. 1182 Port of Aberdeen By Liverpool Classified 7 A 1  
Committee 46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>Metal</u> When put on <u>1846</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, The Caulking of the Bottom at the several parts  
we saw it tried is in bad condition.

Left notice Card recommending that the Ship  
 be hinged in Shous and Bottom properly Caulked.  
 Committee Minute 14<sup>th</sup> Aug 1849  
 Character assigned Good She has been undock<sup>d</sup> without attending to  
the request. We are of opinion that her character  
should be improved Ja<sup>s</sup> Martin W<sup>m</sup> Martin  
with L<sup>ieut</sup> R<sup>ear</sup> Admiral Certificate (if required)

No. 849 Survey held at London Date Aug 4<sup>th</sup> 1849  
 on the 13<sup>th</sup> "Cybele" Master Good  
 Tonnage 334 Built at Mirimichi When built 1841  
 By whom built \_\_\_\_\_ Owners Colling & Co.  
 Port belonging to London Destined Voyage Dominica  
 If Surveyed Afloat or in Dry Dock In Limekiln Dry Dock

Last Survey, No. 14879 Port of London Classified 5 A 1  
S.S. 47. 5 Cont 46. 2 1 mo 49

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper <u>F</u> When put on <u>47</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, Now done. The two diminishing Strakes below Wales also the  
Buttock Planking above Copper dubbed bright. Six Short after Floods in  
Starb<sup>d</sup> Buttock, and three on the Port side up part replaced with new, the  
Butts to be more properly shifted when the Copper is stripped off next  
voyage. She appears eligible to remain  
 Committee Minute 14<sup>th</sup> Aug 1849 as Classed A 1 Ja<sup>s</sup> Martin  
 Character assigned Good W<sup>m</sup> Martin Certificate (if required)