

# ANNUAL SURVEYS.

No. 36 Survey held at London Date July 31<sup>st</sup> 1849  
on the Bk Indefatigable Master Harwood  
Tonnage 509 Built at Richbuck When built 1830  
By whom built \_\_\_\_\_ Owners Harwood  
Port belonging to Whitby Destined Voyage Columbo  
If Surveyed Afloat or in Dry Dock Afloat

Last Survey, No. 14403 Port of London 1840 Classed A.1 S.S. from 1846  
498

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>"</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Deerstakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Oppsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Keelsons <u>"</u>	Copper <u>"</u> When put on <u>1847</u>	Standing & Running Rigging <u>good</u>

General Observations and Opinion Three pair of additional staple standards, new stem timbers & berthing, and appears in good condition to retain her present class

Committee Minute 17<sup>th</sup> Augt 1849  
Character assigned A.1

Certificate (if required)

No. 31 Survey held at London Date August 3<sup>rd</sup> 1849  
on the SS Naomi Frances Master M. Thompson  
Tonnage 160 Built at Sunderland When built 1846  
By whom built \_\_\_\_\_ Owners Huntley  
Port belonging to Sunderland Destined Voyage Dantzic  
If Surveyed Afloat or in Dry Dock Sunderland

Last Survey, No. 3430 Port of Sunderland Classed 7A1  
48

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>Good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>"</u>
Deerstakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Oppsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Keelsons <u>"</u>	Copper <u>"</u> When put on _____	Standing & Running Rigging <u>good</u>

General Observations and Opinion Bottom examined and appears in good condition to continue as classed

Committee Minute 17<sup>th</sup> Augt 1849  
Character assigned A.1

Certificate (if required)



© 2019

Lloyd's Register Foundation

CON627-0091