

REPORT of SURVEY for REPAIRS.

No. 15410 Survey held at London Date 9th June 1847
 in the Sch "Suttana & Selina" Master McEwen
 Tonnage 125 Built at Barking When built 1840
 By whom built Mr Taylor Owners J. Affalo
 Port belonging to London Destined Voyage Mogadore
 If Surveyed Afloat or in Dry Dock in Bull Head Dock

Last Survey, No. _____ Classed 12 AA

Port _____

REPAIRS

at present bottom stripped caulked to the Wales
and bottom recoppered with Yellow Metal on dry
paper - bowsprit unshipped Caulked under and
replaced -

Present Condition of the

Decks <u>Good</u>	Treenails <u>apparently Good</u>	Windlass and Capstan <u>Good</u>
Waterways <u>---</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>---</u>
Comings <u>---</u>	Transoms, Pointers, and Crutches <u>---</u>	Boats <u>two one new</u>
Upper Deck Beams & Fastenings <u>---</u>	Timbers of the Frame <u>---</u>	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings <u>---</u>	Keelsons <u>---</u>	Sails <u>2 sets</u>
Planksheers <u>---</u>	Clamps and Shelves <u>---</u>	Anchors No. of <u>2, 1, 1</u>
Sheerstrakes <u>---</u>	Ceiling <u>---</u>	Cables <u>Sufficient</u>
Topsides <u>---</u>	Rudder <u>---</u>	Hawsers and Warps <u>---</u>
Wales <u>---</u>	<u>Copper Y Metal new on</u>	Standing & Running Rigging <u>---</u>
Plank (Bottom) and Counter <u>---</u>	<u>dry paper 1847</u>	

General Observations and Opinion,

This Vessel is now in most efficient Condition
and may be replaced on her Original Classification

The Amount of Fee.....£ : : is received by me, J. H. H. H.

Certificate (if required) : :

Committee's Minute _____ 18 _____

Character assigned _____



© 2019

Lloyd's Register
Foundation

LON627-0134