

ANNUAL SURVEYS.

No. 465- Survey held at London Date Sept 3rd 1849
on the Bagna "Clara" Master G. Potter
Tonnage 365 Built at Yarmouth When built 1827
By whom built Owners J. Fletcher
Port belonging to London Destined Voyage New Zealand
If Surveyed Afloat or in Dry Dock In Fletcher's Dry Dock

Last Survey, No. 12199 Port of London

Classed A 1
Rest 44.7.46

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways } <u>good</u>	Breasthooks and Stemson } <u>good when seen</u>	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>In good order</u>
Lower Deck Beams & Fastenings } <u>d^o when seen</u>	Keelsons <u>d^o</u>	Sails <u>and sufficient</u>
Planksheers	Clamps and Shelves <u>d^o</u>	Anchors No. of <u>3 11K2</u>
Sheerstrakes <u>d^o</u>	Ceiling <u>d^o</u>	Cables
Topsides <u>d^o</u>	Rudder <u>d^o</u>	Hawsers and Warps
Wales <u>d^o</u>	Copper <u>Y Metal</u> When put on <u>now new</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion.

Now done. The Yellow Metal Sheathing stripped off and renewed upon the Wood Sheathing Aloft and upon Paper below; Caulked Outside from Keel up to Watway Seam.

Committee Minute 18th Sept 1849 she appears to be in good condition

Character assigned Rest 7A1 eligible to remain as Classed A 1

renewed J. A. Martin
Certificate (if required)

No. 174 Survey held at London Date Sept 1849
on the Castle Eden Master
Tonnage 762 Built at Sunderland When built 1842
By whom built Owners J. & F. Jones
Port belonging to London Destined Voyage
If Surveyed Afloat or in Dry Dock Canal Dry Dock

Last Survey, No. 14262 Port of London

Classed A 1

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>good</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good when seen</u>	Timbers of the Frame <u>"</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good when seen</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>good</u>	Anchors No. of <u>"</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>"</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y Metal</u> When put on <u>1849</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Bottom stripped, caulked & sheathed with Yellow Metal overfett, and appears in good condition to continue her present class

Committee Minute 18th Sept 1849

Character assigned 9A1

renewed J. A. Martin
Certificate (if required)