

# ANNUAL SURVEYS.

15498

No. <sup>365</sup> Survey held at London Date October 8 1849  
 on the Bk Alice Maud Master Sinton  
 Tonnage 370 Built at Bideford When built 1845  
 By whom built \_\_\_\_\_ Owners J. Lidgett  
 Port belonging to London Destined Voyage Ceylon  
 If Surveyed Afloat or in Dry Dock Douglas Dock

Last Survey, No. 14379 Port of London

Classed 12 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, Bottom stripped, and caulked, and sheathed with yellow metal  
up to a coarse waft & below over paper, throat of the  
hanging knees to the hold beams between the Mizzen Mast  
& Foremast renewed with yellow metal, and is in very good  
condition to continue as classed

Committee Minute 19th Oct 1849

Character assigned 12 A 1

Certificate (if required)

No. <sup>155</sup> Survey held at London Date Oct 6 to 9 1849  
 on the Bk Thomas Chodwick Master St. Vickerman  
 Tonnage 461 Built at Sunderland When built 1847  
 By whom built \_\_\_\_\_ Owners T. Chodwick  
 Port belonging to London Destined Voyage Adelaide  
 If Surveyed Afloat or in Dry Dock Grange Dock

Last Survey, No. 14480 Port of London

Classed 9 A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Lower Deck Beams & Fastenings	Keelsons	Sails
Planksheers	Clamps and Shelves	Anchors No. of
Sheerstrakes	Ceiling	Cables
Topsides	Rudder	Hawsers and Warps
Wales	Copper	Standing & Running Rigging
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, Stripped and caulked from keel to upper part of wales, treenails  
searched, several bolts in the lower deck beams renewed  
with yellow metal & sheathed with yellow metal over  
felt is in good condition through out and may continue as classed

Committee Minute 23rd Oct 1849

Character assigned 9 A 1

Certificate (if required)