

ANNUAL SURVEYS.

15548

No. ³⁷² on the *Bk John* Survey held at *London* Date *Oct 24 to 27* 18*49*
 Tonnage *372* Built at *Wharfedale* Master *J H Haggland*
 By whom built *362 Yes Custom* Owners *Granberg*
 Port belonging to *Wharfedale* Destined Voyage
 If Surveyed Afloat or in Dry Dock *Douglas Dock*

Last Survey, No. *2018* Port of *Hull* *1849* Classed *5A1*

The present Condition of the

Decks	Treenails <i>good</i>	Windlass and Capstan <i>good</i>
Waterways	Breasthooks and Stemson <i>"</i>	Pumps <i>"</i>
Comings	Transoms, Pointers, and Crutches <i>"</i>	Boats <i>"</i>
Upper Deck Beams & Fastenings	Timbers of the Frame <i>good where seen</i>	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings	Keelsons <i>good</i>	Sails <i>well found</i>
Planksheers	Clamps and Shelves <i>"</i>	Anchors No. of <i>3 Bows 1 Stm 1 Hdg</i>
Sheerstrakes	Ceiling <i>"</i>	Cables <i>well found</i>
Topsides	Rudder <i>"</i>	Hawsers and Warps <i>"</i>
Wales	Copper <i>of Metal</i> When put on <i>1849</i>	Standing & Running Rigging <i>good</i>
Plank (Bottom) and Counter		

General Observations and Opinion *Bottom caulked and sheathed with yellow metal over paper, presents a very firm & good appearance, but has not hanging knees or sides to the photo beams agreeable to the rule Sect 62*

Committee Minute *30th Oct 1849*

Character assigned *5A1*

record ym. JH

W. Middleton

J. P. Martin

Certificate (if required)

No. ²⁷² on the *Bk Liza* Survey held at *London* Date *Oct 27* 18*49*
 Tonnage *296* Built at *Barkby* Master *Simpson*
 By whom built Owners *Robinson & Co*
 Port belonging to *London* Destined Voyage *Jamaica*
 If Surveyed Afloat or in Dry Dock *Youngs Dock*

Last Survey, No. *14603* Port of *London* Classed *A1 Asterisk S546*

The present Condition of the

Decks <i>Good</i>	Treenails	Windlass and Capstan <i>good</i>
Waterways <i>"</i>	Breasthooks and Stemson <i>good</i>	Pumps <i>"</i>
Comings <i>"</i>	Transoms, Pointers, and Crutches <i>"</i>	Boats <i>"</i>
Upper Deck Beams & Fastenings <i>"</i>	Timbers of the Frame <i>good where seen</i>	Masts, Yards, &c. <i>"</i>
Lower Deck Beams & Fastenings <i>"</i>	Keelsons <i>"</i>	Sails <i>well found</i>
Planksheers <i>good</i>	Clamps and Shelves <i>"</i>	Anchors No. of <i>3 Bows 1 Stm 2 Hdg</i>
Sheerstrakes <i>"</i>	Ceiling <i>good</i>	Cables <i>well found</i>
Topsides <i>"</i>	Rudder <i>"</i>	Hawsers and Warps <i>"</i>
Wales <i>"</i>	Copper	Standing & Running Rigging <i>good</i>
Plank (Bottom) and Counter <i>good</i>	When put on	

General Observations and Opinion *Copper patched and is in good condition to retain her present class*

Committee Minute *30th Oct 1849*

Character assigned *A1 Asterisk*

JH

W. Middleton

Certificate (if required)