

ANNUAL SURVEYS.

15550

No. 307 on the "Dr Robert Mathews" Survey held at London Date 19th 26 Oct^r 1849
 Tonnage 265 Built at Sunderland Master W. Staniland
 By whom built _____ Owners Lundies
 Port belonging to London Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Williams Dock

Last Survey, No. 14280 Port of London Classed GA 1

The present Condition of the

Decks <u>Caulked</u> <u>Good</u>	Treenails <u>Good</u>	Windlass and Capstan <u>Good</u>
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>2</u> _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails <u>do</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>3. 1. 1</u>
Sheerstrakes _____	Ceiling _____	Cables <u>Sufficient</u>
Topsides _____	Rudder _____	Hawsers and Warps <u>do</u>
Wales _____	Copper <u>4 Metal</u> When put on <u>Oct^r 1849</u> on felt above & paper below	Standing & Running Rigging <u>do</u>
Plank (Bottom) and Counter _____		

General Observations and Opinion,

At present bottom stripped Caulked and Sheathed with Yellow Metal on felt above & paper below is in efficient Condition and may remain

Committee Minute 2 November 1849 as Clipped St. H. P. H. P.
 Character assigned GA 1 record ym. St. H. P. H. P.

Certificate (if required)

No. 237 on the Sch^r "Ceres" Survey held at London Date 31 Oct^r 1849
 Tonnage 118 Built at Weyford Master W. Robertson
 By whom built _____ Owners J. Brown
 Port belonging to Peterhead Destined Voyage _____
 If Surveyed Afloat or in Dry Dock in Bullhead Dock

Last Survey, No. 9633 Port of London Classed 12 A 1

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats <u>two</u> _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. <u>well</u>
Lower Deck Beams & Fastenings _____	Keelsons <u>Good</u>	Sails <u>found</u>
Planksheers _____	Clamps and Shelves _____	Anchors No. of <u>2. 1. 1</u>
Sheerstrakes _____	Ceiling _____	Cables <u>Sufficient</u>
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper <u>ym</u> When put on <u>Oct^r 1849</u> on paper	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

at present bottom Caulked iron bolts of iron bands cupped with lead and bottom sheathed with Yellow Metal on paper is in efficient Condition

Committee Minute 2 November 1849 and may remain as Clipped St. H. P. H. P.
 Character assigned 12 A 1 record ym. St. H. P. H. P.

Certificate (if required)