

ANNUAL SURVEYS.

No. 80 Survey held at London Date Nov 12 1849
on the Bk Malcolm Master J Sim
Tonnage 237 Built at Whitehaven When built 1834
By whom built Owners Buckham & Sim
Port belonging to Whitehaven Destined Voyage Demerara
If Surveyed Afloat or in Dry Dock Duke Shore Dock

Last Survey, No. 15205 Port of London Restored 1846 Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>good & firm</u>	Timbers of the Frame <u>good & where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>good</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bower 1 Stm 1 Hdg</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y Metal</u> When put on <u>Nov 1849</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>good</u>		

General Observations and Opinion, Bottom caulked and sheathed with yellow metal over paper, all the lodging knee bolts & ribs beams renewed with metal; and is in a very efficient state to retain her present class

Committee Minute 23rd Nov 1849

Character assigned 10 A 1

Certificate (if required)

No. 666 Survey held at London Date Nov 10th 1849
on the Bk Anne Mc Sean Master Robertson
Tonnage 320 Built at When built 1847
By whom built Owners Hambro & Co
Port belonging to London Destined Voyage Calcutta
If Surveyed Afloat or in Dry Dock West India Dock

Last Survey, No. 2877 Port of Glyde 1847 Classed 10 A 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>good</u>	Windlass and Capstan <u>good</u>
Waterways <u>"</u>	Breasthooks and Stemson <u>"</u>	Pumps <u>"</u>
Comings <u>"</u>	Transoms, Pointers, and Crutches <u>"</u>	Boats <u>"</u>
Upper Deck Beams & Fastenings <u>"</u>	Timbers of the Frame <u>good & where seen</u>	Masts, Yards, &c. <u>"</u>
Lower Deck Beams & Fastenings <u>"</u>	Keelsons <u>good</u>	Sails <u>well found</u>
Planksheers <u>"</u>	Clamps and Shelves <u>"</u>	Anchors No. of <u>3 Bower 1 Stm 2 Hdg</u>
Sheerstrakes <u>"</u>	Ceiling <u>"</u>	Cables <u>well found</u>
Topsides <u>"</u>	Rudder <u>"</u>	Hawsers and Warps <u>"</u>
Wales <u>"</u>	Copper <u>Y Metal</u> When put on <u>1847</u>	Standing & Running Rigging <u>good</u>
Plank (Bottom) and Counter <u>"</u>		

General Observations and Opinion, From her good & efficient condition an opinion she may retain her present class

Committee Minute 23rd Nov 1849

Character assigned 10 A 1

Certificate (if required)

