

# ANNUAL SURVEYS.

15082

No. 37 Survey held at London Date 22<sup>nd</sup> Dec 1849  
 on the Brig "Falcon" Master Carnell  
 Tonnage 174 Built at Yarmouth When built 1843  
 By whom built Hamilton Owners Hamilton  
 Port belonging to London Destined Voyage Africa  
 If Surveyed Afloat or in Dry Dock in Hawks Dock

Last Survey, No. 14989 Port of London Classed GA 1

The present Condition of the

Decks <u>Good</u>	Treenails	Windlass and Capstan
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>will</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>found</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>and</u>
Sheerstrakes	Ceiling	Cables <u>Sufficient</u>
Topsides	Rudder <u>bands refitted</u>	Hawsers and Warps
Wales <u>Sheathed with Yellow Metal</u>	Copper <u>When put on 1847</u>	Standing & Running Rigging
Plank (Bottom) and Counter		

General Observations and Opinion, at present new false Stern Post fitted and  
udder bands refitted Yellow Metal Sheathing  
patched. The lower deck fastenings of iron Sheathed  
over with Yellow Metal on felt - as inefficient  
14<sup>th</sup> Jan'y 1850  
 Committee Minute Condition and May Continue as  
 Character assigned GA 1 Clasped  
W. H. Pritchard  
 Certificate (if required)

No. 37 Survey held at London Date 22 Dec 1849  
 on the B.K. "Falcon" Master Jarris  
 Tonnage 217 Built at Sunderland When built 1843  
 By whom built T Crisp Owners T Crisp  
 Port belonging to London Destined Voyage Cape of Good Hope  
 If Surveyed Afloat or in Dry Dock on Crisp's ways

Last Survey, No. 15284 Port of London Classed 10A 1

The present Condition of the

Decks	Treenails	Windlass and Capstan <u>Good</u>
Waterways	Breasthooks and Stemson	Pumps
Comings	Transoms, Pointers, and Crutches	Boats <u>two</u>
Upper Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c. <u>Sufficient</u>
Lower Deck Beams & Fastenings	Keelsons <u>Good</u>	Sails <u>2 Sticks</u>
Planksheers	Clamps and Shelves	Anchors No. of <u>3-1-1</u>
Sheerstrakes <u>Good</u>	Ceiling	Cables <u>Sufficient</u>
Topsides	Rudder	Hawsers and Warps <u>so</u>
Wales	Copper	Standing & Running Rigging <u>on</u>
Plank (Bottom) and Counter	When put on	

General Observations and Opinion, at present bottom stripped Caulked both  
wales and Sheathed with Yellow Metal  
on the bare Plank as inefficient  
14<sup>th</sup> Jan'y 1850  
 Committee Minute Condition and May Continue  
 Character assigned 10A 1 Clasped  
W. H. Pritchard  
 Certificate (if required)