

REPORT of SURVEY for REPAIRS.

15730

No. 19 Survey held at London Date 29 Dec 1849 till 23 Jan 1850
 on the Bk "Fairy Queen" Master W Doyle
 Tonnage 250 Built at Newcastle When built 1808
 By whom built _____ Owners Woodbridge
 Port belonging to London Destined Voyage New Zealand
 If Surveyed Afloat or in Dry Dock in Globe Dock

Survey, No. 14714 Port London Classed *A. 1 S.S. 48

IRS at Present from damage by stress of Weather and Collision
 all new head knee with new tail cheeks & fittings - 9 new
 toughened one length new plank sheer and rails & bulwarks
 on both sides forward - New long boats bought & fitted
 with new fore stay and topmast stays - and ^{doubling of} topsides &
 waterways Caulked - Not from damage doubling
 of wales topsides and sheer strakes scraped bright and
 Caulked - Counter doubled and two iron knees fitted
 on keels of stern timber - one new pump fitted New
 Main Mast & main topmasts and jibboom furnished

ent Condition of the			
ks	<u>Caulked Good</u>	Treenails	Windlass and Capstan
terways	<u>0</u>	Breasthooks and Stemson	Pumps <u>one new</u>
nings	<u>0</u>	Transoms, Pointers, and Crutches	Boats
per Deck Beams & Fastenings		Timbers of the Frame	Masts, Yards, &c.
wer Deck Beams & Fastenings		Keelsons	Sails
anksheers	<u>Doubling</u>	Clamps and Shelves	Anchors No. of
eerstrakes	<u>Scraped bright</u>	Ceiling	Cables
psides	<u>and Caulked</u>	Rudder	Hawsers and Warps
ales		Copper	Standing & Running Rigging
lank (Bottom) and Counter		When put on	

General Observations and Opinion,
 This Vessel is in efficient Condition and
 in our opinion fit for the safe conveyance
 of dry & perishable Cargoes to & from all Ports
 of the World and may

The Amount of Fee £ 1 : — : — is received by me,
 Special..... 4 : 4 : —
 Certificate (if required) : 10 : —

Committee's Minute 1st Feb 1850
 Character assigned Fit for service
 Special Damage £4.4
 Lloyd's Register Foundation
 LON 628 - 0035