

REPORT of SURVEY for REPAIRS.

Change of owner

No. *187* Survey held at *London* Date *Oct 12th* 18*49*
 on the *Mk "Sme Gondie"* Master *Stott*
 Tonnage *234* Built at _____ When built *1834*
 By whom built _____ Owners *Capt Holmwood & Co.*
 Port belonging to *London* Destined Voyage *New York*
 If Surveyed Afloat or in Dry Dock *London Dock*

Last Survey, No. *14318* Port *London* Classed *Resus. 10 7 A1*

REPAIRS

Present Condition of the

Decks <i>Good</i>	Treenails <i>Good</i>	Windlass and Capstan <i>efficient</i>
Waterways _____	Breasthooks and Stemson <i>do</i>	Pumps <i>do</i>
Comings _____	Transoms, Pointers, and Crutches <i>do</i>	Boats <i>do</i>
Upper Deck Beams & Fastenings <i>Secure</i>	Timbers of the Frame <i>when seen do</i>	Masts, Yards, &c. <i>do</i>
Lower Deck Beams & Fastenings <i>do</i>	Keelsons <i>do</i>	Sails <i>do</i>
Planksheers <i>Good</i>	Clamps and Shelves <i>do</i>	Anchors No. of <i>3 DISH</i> <i>do</i>
Sheerstrakes <i>do</i>	Ceiling <i>do</i>	Cables <i>do</i>
Topsides <i>do</i>	Rudder <i>do</i>	Hawsers and Warps <i>do</i>
Wales <i>do</i>	Copper <i>Match</i> When put on <i>1848</i>	Standing & Running Rigging <i>do</i>
Plank (Bottom) and Counter <i>do</i>		

General Observations and Opinion,

She is in good condition and efficient and may remain so classed
Four tenney

The Amount of Fee.....£ *1* : — : — is received by me, *Stott*

Special..... : : —

Certificate (if required) : : —

Committee's Minute *19th Feb 1850*

Character assigned *Best 7 A1*



© 2019

Lloyd's Register

LON 628 0070